



BLUE DIAMOND MEASUREMENT AND CONTROLS, LLC

Measure Head Safety Precautions



As is the case with most mechanical equipment the RMH Enterprises/Blue Diamond Measure Head has pulleys, gears, moving, and sliding components. Tremendous weights, pressures, and often, speeds are associated with wireline logging & perforating. In addition, the nature of the environment the equipment is exposed to enhances the need for a much closer attention to the safety concerns and proper operation.

Please note the following safety guidelines:

1. The protective side covers should remain on the unit during operation at all times. Meshing gears could cause severe injury to fingers and or hands.
2. Care should be taken when removing the center section in and out of the head. Wear protective gloves and keep hands and fingers clear of the slot in the frame to avoid injury.
3. Never place hands or fingers in or around rotating wheels i.e.; measure wheel, guide shivs, or pressure roller as severe injury may occur.
4. Keep hands and fingers clear of entry and exit areas of wireline cable as sudden starts and stops of cable could cause severe injury.
5. Never wear loose clothing and or jewelry when operating equipment.
6. Always take safety precautions and wear the appropriate personal protective equipment when working on or around the wireline measuring components.